ON-OFF HIRE INSPECTION

Data Record Name: OFF-HIRE - 204239 - 104869 Submitted by Jim Greer - Complete	Submitter Name: Kilian Moran kilian.moran@kiewit.com
Date Sent on Device: Sep 26, 2024 7:37:03 AM CDT	
Location:	

EQUIPMENT INFO

INSPECTION TYPE OFF-HIRE

EQUIPMENT CATEGORY CONSTRUCTION OWNED EQUIPMENT

DATE OF ARRIVAL ON JOB Sep 25, 2022

SAP UNIT # 204239

IS THIS A CRANE? No SAP WORK ORDER # 0

MODEL NUMBER 289D3

MANUFACTURER CATERPILLAR MANUFACTURER SERIAL # JX903015

MANUFACTURER SERIAL DATA PLATE IMAGE



MANUFACTURERSERIALDA 1.jpg

PLATE?

NAME OF INSPECTOR Jim Greer

Project Description 104869 - CJ - Shawnee Ash Removal

NO

PROJECT # PERFORMING INSPECTION 104869

KES PROJECT EMAIL kes104869@kiewit.com

DATE OF INSPECTION Sep 26, 2024

SUPERVISOR EMAIL heath.hislop@kiewit.com

MACHINE HOURS 6400
MILEAGE - **IF UNKNOWN TYPE 0**

KILOMETERS - **IF UNKNOWN TYPE 0**	0
TELEMATICS INSTALLED	YES
TELEMATICS REPORTING	YES
LUBE SCHEDULE / PM SCHEDULE UP TO DATE?	YES
RECEIVING PROJECT #	0
Region	CNT1
District	CNTR
TYPE CODE	37-21
TYPE CODE DESCRIPTION	37-21 Skid Steer - Track

SAFETY EQUIPMENT	
SEAT BELT & EXPIRATION DATE	NORMAL
SEAT BELT BEACON	N/A
AMBER SAFETY BEACON	N/A
BLIND SPOT CAMERAS & OBJECT/PEOPLE DETECTION	NORMAL
BACKUP ALARM	NORMAL
ROPS/FOPS	NORMAL
FIRE EXTINGUISHER & EXPIRATION DATE	NORMAL
S.M.V. SIGN	N/A
PINCH POINT PROTECTION & SWING RADIUS BARRICADES IN PLACE	N/A
POSITIVE AIR SHUT OFF INSTALLED	N/A
SECONDARY ESCAPE ACCESS INSTALLED	NORMAL
INSURANCE DOCUMENTS & ON THE SPOT FORM IN GLOVEBOX	N/A
SPILL KIT PRESENT (DIESEL EQUIPMENT, >1 TON TRUCKS, TRUCKS W/ TRANSFER TANKS)	N/A

IMAGES



IMAGES 13_1.jpg

ENGINE

OIL LEAKS NORMAL
COOLANT LEAKS NORMAL
FUEL LEAKS NORMAL

IMAGES



IMAGES_1.jpg

TRANSMISSION/PUMP DRIVE

OIL LEAKS NORMAL

IMAGES



IMAGES 1_1.jpg

HYDRAULICS

HYDRAULIC LEAKS

NORMAL

IMAGES



IMAGES 2_1.jpg

TIRES & UNDERCARRIAGE

HOW MANY TIRES? NONE

FASTENERS NORMAL

OVERALL CONDITION NORMAL IS THE CURRENT CTS REPORT ATTACHED? N/A

IMAGES







IMAGES 8_1.jpg

IMAGES 8_2.jpg

IMAGES 8_3.jpg



IMAGES 8_4.jpg

BUCKET NORMAL BLADE N/A N/A

ON-OFF HIRE INSPECTION PAGE 5 OF 10